





FOAMe IIx 3D Park Flyer Design












































2	
3	
4	

Inch Scale reference, check after printing.



battery..... 5 cen-700 to 1320mAn-En-10ly


* 3 Cell 700-1350m.

Prop(s)


* GWS 12x6 Slow FI

* APC 12x3.8 electr

® Copyright 2005 3Dbatix.com. All rights reserved. rev-4.0305



All airframe parts and control surfaces are cut f





Lighty coat back of plan parts with Spray Adhesive, apply each part to Depron. Carefully cut each out using a strightedge and #11 Xacto.



Carefully cut each out using a strightedge and #11 Xacto.




Dry fit assembly--check alignment.



A Rotary Tool Cutting Adapter is perfect for clean, easy to make, grooves for Fiber Carbon rod wing spar. Glue spar in with RC Z 56 or medium/thick CA.

Look for more

rom 6mm Deporn Foam



bulid tips online at: 3Dbatix.com



Apply trim scheme before final assembly. Zagi tapw works great! It's best to trim each part before assembly.



Assemble using RC Z 56 or medium or thick CA. great for trim.